# Oil Field Environmental Incident Summary

Incident: 20140915104629 Date/Time of Notice: 09/15/2014 10:46 Responsible Party: OXY USA INC. Well Operator: OXY USA INC. Well Name: STATE DVORAK A 2-16-21H-142-96 Field Name: MANNING Well File #: 27958 Date Incident: 9/14/2014 Time Incident: 15:30 Facility ID Number: DUNN Twp: 142 **Rna**: 96 **Sec:** 9 County: Location Description: Submitted By: Dustin Tescher Received By: **Dustin Tescher** Contact Person: 5 GREENWAY PLAZA STE 110 HOUSTON, TX 77046-0506 General Land Use: Well/Facility Site Affected Medium: Well/Facility Soil 3.3 Mile Distance Nearest Occupied Building: Distance Nearest Water Well: 3.3 Mile Type of Incident: Valve/Piping Connection Leak Release Contained in Dike: Yes - On Constructed Well Site Reported to NRC: No **Units** Spilled Recovered Units **Followup Units** Oil **Brine Barrels Barrels** barrels Other **Description of Other Released Contaminant:** Inspected: Written Report Received: 9/17/2014 Clean Up Concluded: 9/14/2014 Risk Evaluation: na

Friday, February 10, 2017 Page 1 of 2

Areal Extent:

### Potential Environmental Impacts:

na

# Action Taken or Planned:

The driver will be retrained on job responsibilities to ensure there is not a repeat event.

Wastes Disposal Location: na

Agencies Involved:

# **Updates**

Date: 9/15/2014 Status: Reviewed - Assigned to Other Agency Author: Roberts, Kris

**Updated Oil Volume:** 

**Updated Salt Water Volume:** 

**Updated Other Volume:** 

**Updated Other Contaminant** 

### Notes:

Release, due to an on-location valve/piping leak, remained on location according to the report. NDIC retains oversight.